
Active Care Quick Start Guide Medical Cobalt/Cobalt X23

Please Read Before Operating!

Your wheelchair is packaged with a packet of tools you will need for initial setup.


Please locate this packet first.

Loosen and remove the two knobs located
on the cover shroud on either side of the seat post opening.




2. Carefully remove the shroud.


Install the seat post. Ensure that the seat post is aligned so that the two flanges with holes are facing the ear of the product. Illawing these flanges rotated drittle any of the possition will nessult in instability in the seat.




From behind the product, looking forward, insert the seat bolt into hole on the left side of the seat post. This bolt is also used to adjust the seat height. Insert the bolt as far into the hole as it will go, making sure that the bolt passes all the way through to the hole on the opposite side. Install the washer and nut and tighten them using the included flat wrench.




Connect the main cable to the battery harness.



6 Replace the cover shroud. Replace and tighten the two knobs removed in Step 1.




Lift the seat and pull the swivel lever up at the same time. Lower the bottom of the seat onto the seat post. Release the lever, swivel the seat and push down on the seat until it locks in place.




NOTE: Get help when placing the seat onto the post to avoid scratching the cover shroud.


Insert the armrests into the attachment points in the seat frame so that the armrests face forward.




Insert and tighten the included star knobs to lockthe armrests into place at the desired width.



Insert the controller's square tube into the tube under the armrest. Tighten the bolt on the underside of the controller arm tube to hold it in place at the desired extension.




Connect the main cable from the controller to the connection port in the product's cover shroud.



Fully charge the wheelchair's batteries by inserting the round charger connector into the battery charging terminal on the front of the wheelchair's controller and inserting the 3-pronged plug into a standard electrical outlet.

Ensure that the 115V/230V switch on the product's battery charger is set to 115V. If the switch is set to 230V, the scooter will not charge properly. Full charging normally takes 6-8 hours, but can take as many as 10 hours depending on the batteries' charge level when starting and the ambient temperature.

Cobalt/Cobalt X23 Quick Start Guide



READ BEFORE UNPACKING

This Quick Start Guide offers basic information on initial product setup only. Read the owner's manual and all supplemental information thoroughly before operating the product for information on safety, battery charging, basic operation, comfort adjustments, disassembly and care and maintenance.

NOTE: The illustrations provided may not reflect your actual unit.

Apparent Loss or Damage

Should visual inspection upon receipt of this shipment show loss or damage, it must be noted on the freight bill or express receipt and signed by the carrier's agent. Failure to do this may result in the carrier refusing to honor claim.

The carrier will forward you the necessary form(s) for filing claim.

Concealed Loss or Damage

When loss or damage is not apparent until the unit is unpacked, then a claim for concealed damage is entered by the receiver. When damage us discovered, make a written request to the carrier for inspection.

Keep all cartons and fillers. You must make this request for inspection within twenty-four (24) hours of the delivery. The carrier will furnish you with an inspection report and the necessary form(s) for filing concealed damage or loss claim. It is the receiver's responsibility to file such claims for concealed damage.